

Monster Energy NASCAR Cup Series					
Infraction Date	Track	Team	Level	Infraction	Penalty
4/30/2017 (post-race inspection)	Richmond	No. 22	L1	Section 20.14.2 Rear Suspension I-4 f <i>Truck Trailing Arm Spacers/Pinion Angle Shims. Spacers/pinion angle shims must conform to the following drawing: A-008-01016d-16 REV. A. Notes: 6 The Truck trailing arm spacer / pinion angle shim mating surfaces must be planar and must be in complete contact with corresponding mating surfaces at all points and at all times.</i> <i>Race finish is encumbered per Section 12.10 Encumbered Race Finishes.</i>	Crew chief (Todd Gordon) has been fined \$50,000 and suspended for two Monster Energy NASCAR Cup Series races. Team has been assessed with the loss of 25 owner points and 25 driver points.
4/30/2017 (post-race inspection)	Richmond	No. 11	Safety	Sections 10.9.10.4: Tires and Wheels <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Mike Wheeler) has been fined \$10,000.

NASCAR XFINITY Series					
Infraction Date	Track	Team	Level	Infraction	Penalty
4/29/2017 (post-race inspection)	Richmond	No. 21	Safety	Sections 10.9.10.4: Tires and Wheels <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Danny Stockman Jr.) has been fined \$10,000 and suspended for the next NASCAR XFINITY Series points race.
4/29/2017 (post-race inspection)	Richmond	No. 3	Safety	Sections 10.9.10.4: Tires and Wheels <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Matt Swiderski) has been fined \$5,000.
4/29/2017 (post-race inspection)	Richmond	No. 46	Safety	Sections 10.9.10.4: Tires and Wheels <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Mark Setzer) has been fined \$5,000.