

NASCAR Sprint Cup Series					
Infraction Date	Track	Team	Level	Infraction	Penalty/Warning
9/10/2016 (post-race inspection)	Richmond	No. 78	P2	Sections 12.1; 20.17.3.1.2 <i>Notes: Failed the post-race Laser Inspection Station (LIS) measurements.</i>	Crew chief (Cole Pearn) has been fined \$15,000; team has been assessed with the loss of 10 championship owner and 10 championship driver points (pre-reset)
9/9/2016 (pre-qualifying inspection)	Richmond	No. 7 (1)	Warning	Failed LIS three times, pre-qualifying	Written Warning and loss of 15 minutes practice time
9/9/2016 (pre-qualifying inspection)	Richmond	No. 16 (2), No. 18 (1), No. 22 (0; penalty served in Richmond), No. 78 (0; penalty served in Richmond)	Warning	Failed LIS twice, pre-qualifying	Written Warning

() -- Total current warnings.