

NASCAR Sprint Cup Series					
Infraction Date	Track	Team	Level	Infraction	Penalty/Warning
11/6/2016 (post-race inspection)	Texas	No. 22	P2	Sections 12.1; 10.11.3.4 <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Todd Gordon) has been fined \$10,000.
11/4/2016 (pre-qualifying inspection)	Texas	No. 4 (2), No. 14 (3), No. 19 (1), No. 78 (1)	Warning	Failed template inspection three times, pre-qualifying	Written Warning and loss of 15 minutes practice time
11/4/2016 (pre-qualifying inspection)	Texas	No. 47 (2)	Warning	Failed LIS three times, pre-qualifying	Written Warning and loss of 15 minutes practice time
11/6/2016 (pre-race inspection)	Texas	No. 3 (3), No. 23 (3)	Warning	Failed LIS twice, pre-race	Written Warning
11/4/2016 (pre-race qualifying)	Texas	No. 3 (3), No. 16 (0; penalty served in Texas)	Warning	Failed LIS twice, pre-qualifying	Written Warning
11/4/2016 (pre-qualifying inspection)	Texas	No. 6 (0; penalty served in Texas), No. 11 (0; penalty served in Texas), No. 18 (2), No. 20 (1), No. 41 (1), No. 83 (2)	Warning	Failed template inspection twice, pre-qualifying	Written Warning and loss of 15 minutes practice time

NASCAR XFINITY Series					
Infraction Date	Track	Team	Level	Infraction	Penalty/Warning
11/5/2016 (post-race inspection)	Texas	No. 62	P2	Sections 12.1; 20.17.3.2.2 <i>Note: Race finish is encumbered per Section 12.10 Encumbered Race Finishes*. Post-race incorrect ground clearance and/or body heights measurements.</i>	Crew chief (Shane Wilson) has been fined \$10,000; team has been assessed with the loss of 10 championship owner and 10 championship driver points.
11/5/2016 (post-race inspection)	Texas	No. 88	P2	Sections 12.1; 20.17.3.2.2 <i>Note: Race finish is encumbered per Section 12.10 Encumbered Race Finishes*. Post-race incorrect ground clearance and/or body heights measurements.</i>	Crew chief (Dave Elenz) has been fined \$10,000; team has been assessed with the loss of 10 championship owner points.
11/5/2016 (post-race inspection)	Texas	No. 1	P2	Sections 12.1; 10.11.3.4 <i>Note: Lug nut(s) not properly installed.</i>	Crew chief (Kevin Meendering) has been fined \$5,000.
11/5/2016 (pre-race inspection)	Texas	No. 18 (2)	Warning	Failed template inspection four times, pre-race	Written Warning and loss of 15 minutes practice time

11/5/2016 (pre-race inspection)	Texas	No. 3 (2), No. 20 (2)	Warning	Failed template inspection three times, pre-race	Written Warning
11/5/2016 (pre-race inspection)	Texas	No. 2 (2), No. 88 (1)	Warning	Failed LIS twice, pre-race	Written Warning

NASCAR					
Infraction Date	Track	Team/Member	Level	Infraction	Penalty/Warning
11/3/2016	N/A	Michael S. Rathje	Behavioral (SAP)	Sections 12.1; 19	Indefinite suspension
11/7/2016	N/A	Michael L. Hubert	Behavioral (SAP)	Sections 12.1; 19	Indefinite suspension

() -- Total current warnings.

* -- Non-win encumbered finishes would factor into tie-breaker scenarios only.